



# **50A MIDI Fuse Kit** FK50



## **50A MIDI FUSE KIT**

The FK50 is designed to provide for a simple, neat fuse installation for dual battery systems. The FK50 is perfect for the TVMS Rogue (TVMS1240) powering wiring loom installation and the Manager30 (BMS1230S3) DC input installation.



#### **KIT CONTENTS**

No.	Part	Quantity
1	50 A MIDI Fuse	2
2	Fuse Holder	1
3	Nut and Spring Washer to suit Fuse Holder	2
4	Lug	2
5	Heatshrink	2

<sup>\*</sup>The Lugs provided are intended for a 16 mm² cable. If using a smaller cable gauge, insert with conductor foldback; if using larger cable gauge, source a larger lug.

#### LIMITED WARRANTY

For full warranty terms and conditions, visit the Warranty page of the REDARC website. Refer to the web address and contact details applicable to your region.

# Australia, New Zealand & Europe www.redarc.com.au/warranty

REDARC Electronics Pty Ltd 23 Brodie Road (North), Lonsdale SA 5160 Australia

 Australia
 +61 8 8322 4848

 New Zealand
 +64 9 222 1024

 UK & Europe
 +44 (0)20 3930 8109

# North America www.redarcelectronics.com/warranty

REDARC Corporation c/o Shallco, Inc. 308 Component Dr. Smithfield, NC 27577 USA

Electronics Ptv Ltd.

USA +1 (704) 247 5150 Canada +1 (604) 260 5512 Mexico +52 (558) 526 2898

Design and specifications are subject to change without notice.

Copyright © 2022 REDARC Electronics Pty Ltd. All rights reserved.

REDARC® and THE POWER OF REDARC® are trademarks of REDARC

# **LUG AND HEATSHRINK ASSEMBLY**

Strip the end of the cable back enough to ensure the insulation does not enter the barrel of the Lug when fully inserted.



Slide the Heatshrink over the cable.

Insert the stripped wires into the barrel of the Lug.

Crimp the Lug using the correct crimping tool.

Slide the Heatshrink to partially cover the Lug, leaving the Lug tongue exposed.

Shrink the heat shrink.

# **FUSE KIT ASSEMBLY**


Order of installing Bolt in the Fuse Holder:

- 1. MIDI Fuse
- 2. Lug with Heatshrink and cable
- 3. Spring Washer




# **TVMS ROGUE INSTALLATION**

Power Wiring Loom Wiring



## **MANAGER30 INSTALLATION**

DC Input Wiring Connection





#### CONTACT

## **Tech Support**

1300 REDARC

#### **Head Office**

+61 8 8322 4848

#### **New Zealand**

+64 9 222 1024

#### **UK & Europe**

+44 (0)20 3930 8109

#### USA

+1 (704) 247 5150

#### Canada

+1 (604) 260 5512

#### Mexico

+52 (558) 526-2898

#### redarcelectronics.com

INST210-3 EN